

ProductInformation

MUCICARMINE STAIN

LEICA AutoStainer XL Stainer

Procedure HT30

Station 1	Station 2	Station 3	Station 4	Station 5	Station 6	Station 7	W1	W2	W3	W4	W5	
Xylene 1 min, 30 sec	Xylene 1 min, 30 sec	Xylene 1 min, 30 sec	100% Alc 1 min, 30 sec	100% Alc 1 min, 30 sec	95% Alc 30 sec	80% Alc 30 sec	Wash 3 min, 30 sec	Wash 15 sec	Wash 2 min, 30 sec	Wash 3 min	Wash 2 min	Oven
End	Station 18 Xylene 2 min	Station 17 Xylene 1 min, 30 sec	Station 16 100% Alc 1 min	Station 15 100% Alc 30 sec	Station 14 100% Alc 10 sec	Station 13 95% Alc 5 sec	Station 12 Not Used	Station 11 Not Used	Station 10 Tartrazine 20 sec	Station 9 Muci- carmine 30 min	Station 8 Weigert's Hem 5 min	Hold